

AD-A105 311

REITZ AND JENS INC ST LOUIS MO

NATIONAL DAM SAFETY PROGRAM, GOESSLING DAM (MO 30852), MISSOURI--ETC(U)

NOV 76 H M REITZ, J J BAILEY


F/6 13/13

DACW43-78-C-0162

UNCLASSIFIED

NL

1 OF 1
AD A
TOTAL



1

MO 30852A

DTIC
ELECTE
OCT 9 1981


DUPLICATE FILE COPY

Approved for public release
Distribution Unlimited

81 707 109

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A105 311	
4. TITLE (and Subtitle)		5. TYPE OF REPORT & PERIOD COVERED
Phase I Dam Inspection Report National Dam Safety Program Goessling Dam (MO 30852) St. Louis County, Missouri		Final Report
7. AUTHOR(s)		6. PERFORMING ORG. REPORT NUMBER
Reitz & Jens, Inc.		
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		DACW43-78-C-0162
11. CONTROLLING OFFICE NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE
National Dam Safety Program, Goessling Dam (MO 30852), Missouri - Kansas City Basin, St. Louis County, Missouri. Phase I Inspection Report.		11 November 1978
16. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		13. NUMBER OF PAGES
Approved for release; distribution unlimited.		Approximately 25
		15. SECURITY CLASS. (of this Report)
		UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)		
Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)		
This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 NORTH 12TH STREET
ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: Goessling Dam, MO ID No. 30852
Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Goessling Dam.

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 25 percent of the Probable Maximum Flood.
- 2) Overtopping could result in dam failure.
- 3) Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY: SIGNED 8 FEB 1979
Chief, Engineering Division Date

APPROVED BY: SIGNED 12 FEB 1979
Colonel, CE, District Engineer Date

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DTIC
S OCT 9 1981
D

PHASE I REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam	Paul Goessling Dam
State Located	Missouri
County Located	St. Louis County
Stream	Augusta Tavern Creek
Date of Inspection	27 October 1978

The Paul Goessling dam was inspected by an interdisciplinary team of engineers from Reitz & Jens, Inc. under contract with the St. Louis District Corps of Engineers. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.


The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and State agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as a small dam with a high downstream hazard potential. The estimated zone from failure of the dam extends one mile downstream from the dam.


Failure would threaten the life and property of three families and cause appreciable damage to associated buildings, one county road and one power transmission line.

Our inspection and evaluation indicates that the dam is deficient in that the spillway is inadequate. Considering the small volume of water impounded, the large floodplain downstream and the three groups of farm buildings downstream, one-half Probable Maximum Flood (PMF) is the appropriate spillway design flood. The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions reasonably possible in the region. A 20% PMF will begin to overtop the dam. The lake and spillway are adequate to contain a 100-year flood which is a flood that has a 1% chance of being equalled or exceeded in any given year.

Other deficiencies noted by the inspection team were tree growth on the upstream and downstream slopes of the dam and lack of erosion protection on the upstream slope and in the spillway of the dam. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency. A real deficiency to the owner which does not have an adverse effect upon the safety of the dam as evaluated in a Phase I Inspection is the inability to maintain even a reasonably full reservoir.


We recommend the owner take action to correct or control the deficiencies described.


HENRY M. REITZ, President
Reitz & Jens, Inc.


JOHN J. BAILEY, SR., Vice President
Chief Engineer
Reitz & Jens, Inc.



OVERVIEW - 30852



PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
Paul Goessling Dam, MO. ID No. 30852

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	2
SECTION 2 - ENGINEERING DATA		
2.1	Design	4
2.2	Construction	4
2.3	Operation	4
2.4	Evaluation	4
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	5
3.2	Evaluation	6
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	7
4.2	Maintenance of Dam	7
4.3	Maintenance of Operating Facilities	7
4.4	Description of Any Warning System in Effect	7
4.5	Evaluation	7
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	8
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	10
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	11
7.2	Remedial Measures	11
APPENDIX		
A	Hydrologic Computations	A-1

TABLE OF CONTENTS
(Cont.)

LIST OF PLATES

<u>Plate No.</u>	<u>Title</u>
1	Overview - Lake and Environs
2	Location and Vicinity Map
3	Plan and Profile Sheet (in pocket on back cover)
A-1 (5 sheets)	Hydrologic and Hydraulic Computations (HEC-1 Input and Output)

LIST OF INDICES AND PHOTOGRAPH NUMBERS

<u>Index No.</u>	<u>Title</u>
1	Index of Dam Photos (D-1 through D-12)
2	Index of Panorama Photos (P-1 through P-6)
3	Index of Spillway Photos (S-1 through S-8)
4	Index of Valley Below Dam Photos (V-1 through V-3)

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer, contracted with Reitz & Jens, Inc. (Contract DACW43-78-C-0162) for a safety inspection of the Paul Goessling Dam, MO. ID No. 30852.

b. Purpose of Inspection The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

c. Evaluation Criteria Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams". These guidelines were developed with the help of several Federal agencies and many State agencies, professional engineering organizations and private engineers.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam and Appurtenances The dam is an earth structure built prior to 1961 in the rolling topography on a tributary of Augusta Tavern Creek.

The soils are Union Silt Loam overlying shallowest bedrock of the lowest strata in the Meramecian Series of the Mississippian System.

The slopes in the watershed are steep in the hillsides and gentle in the valley bottom. Land use in the watershed is about 75% virgin woods and 25% clear and in pasture or lake area. There is an emergency spillway at the west abutment of the dam, an earth channel excavated in virgin soil.

Pertinent physical data are given in paragraph 1.3 below.

Topography in the vicinity of the dam is shown on Plate 3.

b. Location The dam is located in the extreme west of St. Louis County Missouri in the NW $\frac{1}{4}$ of the SW $\frac{1}{4}$ of Section 18, T44N, R3E, as shown on Plate 2. The dam and lake are shown on the Eureka Quadrangle Sheet, 1954 Edition, Revised 1968.

c. Size Classification Criteria for determining the size classification of dams and impoundments are presented in the guidelines referred to in paragraph 1.1.c above. Based on these criteria, this dam and impoundment is in the Small Size Category.

d. Hazard Classification Guidelines for determining hazard classification are presented in the same guidelines referred to in paragraph c above. Based on referenced guidelines, this dam is in the High Hazard Classification.

e. Ownership The dam is owned by Paul Goessling, 17 Upper Ladue Rd., St. Louis, MO, 63124.

f. Purpose of Dam This dam forms a 7.8+ acre recreational lake.

g. Design and Construction History The inspection team was unable to find any design data on this dam. It was reported that construction on the dam began in 1954 and water impoundment commenced in 1961.

h. Normal Operating Procedure Normal rainfall, runoff, transpiration and evaporation and seepage from the reservoir all combine to maintain a water surface noticeably below the spillway crest. Brush growth on the lake-side slope 10 feet below the spillway crest suggests the lake surface seldom rises above this point. The maximum water depth ever experienced at the spillway is unknown.

1.3 PERTINENT DATA

a. Drainage Area - 154 acres

b. Discharge at Damsite

(1) All discharge at the damsite is through an uncontrolled spillway.

(2) Estimated experienced maximum flood at damsite - unknown.

(3) Estimated ungated spillway capacity at maximum pool elevation - 175 cfs.

c. Elevation (Feet Above M.S.L.)

(1) Top of dam - varies from 633 to 631.8+ (see Plate 3).

(2) Spillway crest - 629

(3) Streambed at centerline of dam - 596.6 (est.)

(4) Maximum tailwater - unknown.

d. Reservoir Length of maximum pool - 1,450 feet +.

e. Storage (Acre-Feet) Top of dam - 191 acre feet.

f. Reservoir Surface (Acres)

(1) Top of dam - 11.9

(2) Spillway crest - 9.6 (est.)

g. Dam

(1) Type - earth embankment

(2) Length - 425 feet

(3) Height - 32 feet maximum (from survey).

(4) Top width - 15 feet

(5) Side Slopes -

(a) Downstream - 1V on 2.9H (determined by survey).

(b) Upstream - 1V on 4H.

(6) Zoning - unknown

(7) Impervious Core - unknown

(8) Cutoff - unknown

(9) Grout curtain - unknown.

h. Diversion and Regulating Tunnel - None

i. Spillways One emergency spillway on the west end.

j. Regulating Outlets - None

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

No design data were found to be readily available (see paragraph 1.2.g).

2.2 CONSTRUCTION

The dam was constructed before 1961.

2.3 OPERATION

The maximum loading on the dam is unknown. The lake level drops from severe leakage into the lake bottom during average precipitation of 38 inches per year.

It appears, from the condition of the emergency spillway, that it has not been used for any sizeable discharge since completion.

2.4 EVALUATION

a. Availability The present owner, who also paid for the original dam construction to create a lake, did not appear to have any records of the design or construction. The owner verbally recollected at least one visit by persons from a public agency.

b. Adequacy The engineering data available were inadequate to make a detailed assessment of design, construction and operation. The owner should have an engineer, experienced in design of dams, perform detailed seepage and stability analyses. An investigation of probable locations, extent and permeability characteristics of waterloss areas in the reservoir is indicated if the owner hopes to maintain a reservoir as originally planned.

However, for the size of dam, materials used and measurements taken, a satisfactory hydrologic/hydraulic evaluation for a full reservoir situation resulted.

c. Validity This report is primarily for safety through maintenance and operation and the conclusions and evaluation for this Phase I Inspection are considered adequate for the definitive statement in this report.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General A visual inspection of the Goessling dam was made on 27 October 1978. This followed two days of field measurements by a survey party on 11 and 14 August 1978. The training and experience of personnel in these inspections included hydraulic/hydrologic engineering, soils and materials engineering, surveying and structural engineering. This section only states those aspects visually observed during the inspection and does not comment upon items reported to have been installed but which were not evident during August and October.

b. Dam The dam is an earth dam. It has a top width of 16 feet (D-2, D-9). Downstream slope is 1V on 3H (D-1); upstream slope is 1V on 3H (D-3, D-11). The height is 32 feet, length approximately 435 feet. The top of dam is essentially level (D-6); elevations vary about one foot. During the field inspections and surveys the water surface in the reservoir was between 15 and 20 feet below the top of the dam (D-3, D-10, D-11, D-12). Both the downstream and upstream surfaces were covered with vegetation (D-1, D-9, D-11, D-12). There was no erosion protection on the reservoir side of the dam (D-3, D-11, D-12). However, the very low lake level reduced the drag of wind blowing across the water; no signs of erosion from waves or other sources on the lake side of the dam were visible. A few saplings were visible on the downstream face of the dam (D-6, D-8), as was some underbrush near the west end (D-1).

On the upstream face of the dam some approximately second-year saplings and underbrush as well as tall weed growth could be seen (D-3, D-11, D-12). These indicate the approximate lake elevations during recent years. The crest of the dam is a heavy luxuriant turf (D-2).

Visual observations for indications of existing seepage were by inspection of the downstream slope of the dam and contiguous areas beyond its toe. No hydrophilic plant growth nor any wet areas were found. While it is apparent that the reservoir has not stayed full or nearly full following wet seasons, the absence of any signs indicating seepage just mentioned can be the direct result of low lake levels. Consequently, the dry downslope portions of the dam with the low reservoir area do not assure freedom from through-seepage or underseepage potentials.

No digging or burrowing animal activity was observed.

c. Spillways There is no primary pipe spillway in the dam. The emergency spillway is at the west end of the dam (S-1, S-4, S-5). The control elevation is about three feet below the top of dam. This spillway is in virgin soil and had a low confining dike (S-3, S-6, S-7) along its east side where, in a part of its alignment, the natural grade was below the nearby top of dam. The spillway has a longitudinal slope of about 3% and is 200 feet long from its high point on the centerline of the dam (S-7). Some very minor erosion paths were visible at the lower end of the spillway that led parallel to the dam downslope (S-2, S-8), rather than following the alignment of the spillway. These, however, appeared to be the result of overland flow from the areas upslope, naturally adjacent to the spillway, rather than from water from the lake going over the spillway.

In the seven weeks between the field survey and dam inspection, the water level in the reservoir dropped two feet. For the very low lake level, the visual impression of shoreline and related conditions in the reservoir would not necessarily be indicative of potential erosion, stability or similar properties. The low lake level, obviously, indicates excessive loss into the bottom of the reservoir. Whether this loss is through the soil mantle or into the shallowest bedrock, it cannot be determined from a Phase I inspection.

d. Reservoir Areas The water storage in the lake is only about one-fourth its capacity (P-1 through P-5).

e. Downstream Channel This channel drains northwardly through a pasture in which there is a horse ring (V-3). Flow over the emergency spillway would reach this channel approximately 100 yards from the centerline of the dam (V-1, V-3).

3.2 EVALUATION

Site observations show a significant problem of loss of water. The site conditions which prevent filling the lake and keeping it nearly full except for abstractions due to evaporation, prevent assessment of potential seepage and bank erosion. Erosion of the bottom of the emergency spillway with aggravated discharge resulting is recognized as a probability.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

There are no controlled outlet works for this dam; therefore, no regulating procedures exist. The pool is controlled by rainfall, runoff, evaporation, seepage into the reservoir sides and bottom, and capacity of the uncontrolled spillway.

4.2 MAINTENANCE OF DAM

Based on the amount of brush and size of saplings on the slopes, these have not had brush cut yearly. The spillway has no erosion protection.

4.3 MAINTENANCE OF OPERATING FACILITIES

No operating facilities exist at this dam.

4.4 DESCRIPTION OF ANY WARNING SYSTEM IN EFFECT

The inspection team is not aware of any existing warning system for this dam.

4.5 EVALUATION

The potential hazards from this dam result from the deficient capacity of its emergency spillway as discussed in section 5.1.d.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

a. Design Data No design data are available.

b. Experience Data The drainage area is developed from USGS Eureka Missouri Quadrangle. Also available are 1"=2000' aerial stereo pairs taken on 9 April 1977, by Surdex Corporation. The lake area is measured on a 1"=200' enlargement of a portion of one of these photographs and shown on Plate 1. The spillway and dam layout are from surveys made during the inspection.

c. Visual Observations

1) The spillway and exit channel are located at the southwest end of the dam. Spillway has a bottom width of about 20 feet, 1V to 10H side slopes and is about two feet deep.

2) No drawdown facilities are available to evacuate the pool.

3) Maximum spillway releases may endanger the integrity of the dam (see paragraph 3.2).

d. Overtopping Potential

1) Although the lake seems to remain well below spillway elevation, prudent engineering analysis requires that spillway capacities be evaluated on the basis of a reservoir full to the spillway crest. On this basis the spillways are too small to pass the minimum required flood of the probable maximum without overtopping. The probable maximum flood is defined as the flood discharge expected from the most severe combination of critical meteorological and hydrologic conditions reasonably possible in the region. The dam will start to be overtopped by a flood equal to 20% of the PMF. The PMF will overtop the dam to a maximum depth of about 1.2 feet. The depth will vary to zero across the dam because of the sloping crest. A width of 300 feet of dam crest will be subject to some overtopping flow. Maximum rate of flow over the dam crest will be subject to some overtopping flow. Maximum rate of flow over the dam crest will be about 500 cubic feet per second. Overtopping flow will have a duration of about 2 hours. The existing lake and spillway will contain a 100-year frequency flood below the crest of the dam.

According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, the 100-year frequency flood is only adequate for a low hazard dam of small size.

2) At the current pool elevation 14.1 feet below the spillway crest, the lake has capacity to retain a one-day 100-year flood without reaching the spillway crest. Assuming a start at the current pool elevation, overtopping of the dam would begin to occur for a flood equal to 35% of the one-day PMF. Because a drawdown tube is absent, there is no assurance the pool will remain at the current elevation. In the future, it is possible that the reservoir will be full at the beginning of a period of intense rainfall. Therefore, the statements in this paragraph cannot justify the lack of adequate spillways but can be used to evaluate the urgency for necessary correction.

3) The effect from rupture of the dam could extend approximately one mile downstream of the dam. There are three inhabited homes downstream of the dam which could be severely damaged and lives of the inhabitants could be lost should failure of the dam occur. A county road and power transmission line are also in the damage zone.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations Visual observations which adversely affect the structural stability of this dam are discussed in Section 3, paragraph 3.1.b.

b. Design and Construction Data No design or construction data relating to the structural stability of the dam were found.

c. Operating Records No appurtenant structures requiring operation exist at this dam.

d. Post Construction Changes No post construction changes, other than those referred to in a above, exist which will affect the structural stability of the dam.

e. Seismic Stability Considering the seismic zone (2) in which this dam is located, an earthquake of this magnitude is not expected to cause a structural failure of this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

a. Safety The spillway is inadequate to pass the required one-half Probable Maximum Flood (PMF). The dam will begin to be overtopped by a flood of 20 percent of the PMF.

The reservoir and principal spillway are adequate to contain a flood which has a 1% chance of being exceeded (100-year flood) in any given year.

Several items were noted during visual inspection by the inspection team which should be corrected or controlled. The growth of trees on the upstream and downstream slopes of the dam is a safety deficiency. An armor-coat to protect the reservoir slope of the dam against wave-wash is needed. Erosion protection for the spillway is deficient. However, none of these is of serious concern until the degree of leakage from the reservoir is substantially reduced.

The stability of and seepage conditions on the downstream slope should be investigated within the first season by an engineer experienced in design of dams after the reservoir leakage is substantially reduced.

b. Adequacy of Information Due to the lack of engineering design and construction data, the conclusions in this report were based on performance history and external visual conditions. The inspection team considers these data sufficient to support the conclusions herein. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency.

c. Urgency The remedial measures recommended in paragraph 7.2 should be accomplished in the near future.

d. Necessity for Phase II Based on the results of the Phase I Inspection, no Phase II Inspection is recommended.

e. Seismic Stability This dam is located in seismic zone 2. An earthquake of this magnitude is not expected to be hazardous to this dam.

7.2 REMEDIAL MEASURES

a. The leakage from the reservoir does not adversely affect the stability of the dam. Therefore, remedial measures are not a requirement of a Phase I report. The inability to maintain a lake level as desired is a definite (but separate from Phase I hazard assessment) concern to the owner.

b. Stability and Seepage Analyses The owner should have an engineer experienced in design and construction of dams prepare seepage and stability analyses.

c. O&M Maintenance and Procedures The following O&M maintenance and procedures are recommended:

(1) Spillway size and/or height of dam should be increased to pass the 50 percent PMF. In either case, the spillway should be protected to prevent erosion.

- (2) Remove vegetation growth on the downstream slope of the dam.
- (3) After removal of existing tree growth, vegetation on the dam should be periodically cut.
- (4) Control growth of vegetation on the dam.
- (5) Fill, grade, fertilize, seed and mulch the erosion channels on the downstream slope. If these are allowed to continue to erode, eventual sloughing and sliding of the downstream face of the dam may occur.
- (6) Build and maintain an erosive-resistant sill in the control section of the spillway and remove the humps and irregularities in the spillway channel.
- (7) A detailed inspection of the dam should be made periodically by an engineer experienced in design and construction of dams. Records should be kept of these inspections and major maintenance.
- (8) The slope of the dam on the reservoir side should be protected against erosion.

APPENDIX A
HYDROLOGIC COMPUTATIONS

HYDROLOGIC AND HYDRAULIC ANALYSIS METHODOLOGY

1. The hydrologic analysis used in development of the overtopping potential is based on applying a hypothetical storm to a unit hydrograph to obtain the inflow hydrograph for a reservoir routing. The Probable Maximum Precipitation for those dams in the high hazard potential category is derived and determined from regional charts prepared by the National Weather Service in "Hydrometeorological Report No. 33". Reduction factors have not been applied. A 24-hour storm duration is assumed with the 24-hour rainfall depths distributed over 6-hour periods in accordance with procedures outlined in EM 1110-2-1411 (SPF Determination). The maximum 6-hour rainfall period is then distributed to hourly increments by the same criteria. Within-the-hour distribution is based upon NOAA Technical Memorandum NWS HYDRO-35. The non-peak 6-hour rainfall periods are distributed uniformly. All distributed values are arranged in a critical sequence by the SPF criteria. The final inflow hydrograph is produced by deduction of infiltration losses appropriate to the soil, land use and antecedent moisture conditions.

2. The reservoir routing is accomplished by using Modified Puls routing techniques wherein the flood hydrograph is routed through lake storage. Hydraulic capacities of the outlet works, spillway and crest of dam are used as outlet controls in the routing. Storage in the pool area is defined by an elevation-area curve. The hydraulic capacity of the spillways is defined by an elevation-discharge curve. The hydraulic capacity of the sloping top of dam is defined by a triangular broad-crested weir equation.

3. Dam overtopping analysis has been conducted by hydrologic methods for this dam and lake. This computation determines the percentage of the PMF hydrograph that the reservoir can contain without the dam being overtopped. An output summary in the hydrologic appendix displays this information as well as other characteristics of the simulated dam overtopping.

4. The above methodology has been accomplished for this report using the systemized computer program HEC-1 (Dam Safety Version), July 1978, prepared by the Hydrologic Engineering Center, U.S. Army Corps of Engineers, Davis, California. The numeric parameters estimated for this site are listed on Plate 1A. Definitions of these variables are contained in the "User's Manual" for the computer program.

5. The discharge in the spillway was calculated using critical depth at the control section near where the dam centerline crosses the spillway channels, allowing 0.2 velocity head for non-uniform velocity distribution, velocity transition losses and friction in the short approach channel. This is equivalent to calculating the spillway as a broad-crested weir with a discharge coefficient of 2.80.

6. The average longitudinal slope of top of dam was determined by plotting length of crest subject to overflow for incremental increases in lake elevation above the lowest crest elevation. The "Z" value thus obtained (increase in lineal feet of crest subject to overflow per foot of rise in the lake) was then used in the triangular broad-crested weir equation: $Q = C*0.4*Z*H^{2.5}$.

 FLOOD HYDROGRAPH PACKAGE (HFC-1)
 DAM SAFETY VERSION JULY 1978
 (LAST MODIFICATION 3 AUG 78)

```

1 A ***** ID # 30852 PAUL GOESSLING DAM ** AND 515 FOR USGS FLV *
2 A ***** DAM SAFETY PROGRAM - U. S. CORPS OF ENGINEERS *****
3 A ***** PFJT7 @ JENS. INC. - AUGUST 1978 *****
4 R 2AR 0 5 -0 -0 -0 -0 -4 -0
5 I 5
6 I 1
7 J1 0.10 0.15 0.20 0.25 0.30 0.35 0.40 0.50 1.00
8 K 0 ***** INFLOW HYDROGRAPH - SCS METHOD *****
9 I *****
10 M 1 2 0.240
11 P 24.8 101 120 130
12 T
13 W2 0.20
14 X -0.10 2.0
15 K 1 0.2
16 I ***** RESERVOIR ROUTING - RATING CURVE SUPPLIED - SLOPING DAM *****
17 Y
18 Y1 1
19 Y4 114.1 114.5 115.0 115.5 116.0 116.5 117.0 117.5 118.0 118.5
20 Y4 119.0 119.5
21 Y5 0 38 92 140 300 440 610 810 1060
22 Y5 1325 1610
23 SA 0.00 2.98 4.34 7.35 11.94 16.53
24 SE AK 100 105 125
25 SS 114.1 3.0 2.5 96
26 SD 116.4
27 K 99

```

TABLE A-1
 Sheet 1 of 5

 FLOOD HYDROGRAPH PACKAGE (HFC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 3 AUG 78

QIN DATE 10/02/78.
 TIME 11.50.16.

***** ID # 30852 PAUL GOESSLING DAM ** ADD 515 FOR USGS FLEV *
 ***** DAM SAFETY PROGRAM - U. S. CORPS OF ENGINEERS *****
 ***** RFLTZ # JENS. INC. - AUGUST 1978 *****

JOB SPECIFICATION
 NO NHR NMN IDAY IMR IMIN METRC IPLT IPRT NSTAN
 288 0 5 -0 -0 -0 -0 -4 -0
 JOPER NNT LROPT TRAFF
 5 -0 -0 -0

MULTI-PLAN ANALYSIS TO BE PERFORMED

QTTOS= .10 .15 .20 .25 .30 .35 .40 .50 1.00
 NPLAN= 1 NPTIO= 9 LRTIO= 1

SUR-AREA RUNOFF COMPUTATION

***** INFLOW HYDROGRAPH - SCS METHOD *****

ISTAO TCOMP IFCON ITAPE JPLT JPRT TNAME TSTAGE TAUUTO
 1 0 -0 -0 1 3 1 -0 -0

HYDROGRAPH DATA

IMYNG IUNG TAREA SNAP TRSNA TRSPC RATIO ISNOW ISAME LOCAL
 1 2 .24 -0.00 .24 1.00 -0.00 -0 -0 1 -0

PRECIP DATA

SPFF PMS R6 R12 R24 R48 R72 R96
 -0.00 24.00 101.00 120.00 130.00 -0.00 -0.00 -0.00

LOSS DATA

LROPT STOKR DLTKR RTIOL FRAIN STOKS RTIOX STPTL CNSTL ALSMV RTIMP
 -0 -0.00 1.00 -0.00 -0.00 1.00 -1.00 -0.00 -0.00 .03

CURVE NO = -80.00 WETNESS = -1.00 EFFECT CN = 80.00

UNIT HYDROGRAPH DATA

TC= -0.00 LAG= .20

RECESSION DATA

STRTIO= -0.00 ORCSN= -.10 RTIOR= 2.00

UNIT HYDROGRAPH 14 END OF PERIOD ORIGINATES. TC= 1 -0.00 HOURS. LAG= .20 VOL= 1.00 13.
 117. 386. 478. 382. 213. 122. 69. 40. 23.

MO.DA HR.MN PERIOD RAIN EXCS LOSS MO.DA HR.MN PERIOD RAIN EXCS LOSS COMP 0

MO,DA	HR,MN	PERIOD	RAIN	EXCS	LOSS	COMP 0	END-OF-PERIOD FLOW	HR,MN	PERIOD	RAIN	EXCS	LOSS	COMP 0
1.01	05	1	.01	.00	.01	0.	1.01	12.05	145	.21	.19	.02	124.
1.01	.10	2	.01	.00	.01	0.	1.01	12.10	146	.21	.19	.02	174.
1.01	.15	3	.01	.00	.01	0.	1.01	12.15	147	.21	.19	.02	236.
1.01	.20	4	.01	.00	.01	1.	1.01	12.20	148	.21	.19	.02	287.
1.01	.25	5	.01	.00	.01	1.	1.01	12.25	149	.21	.19	.02	316.
1.01	.30	6	.01	.00	.01	1.	1.01	12.30	150	.21	.19	.02	333.
1.01	.35	7	.01	.00	.01	1.	1.01	12.35	151	.21	.19	.02	343.
1.01	.40	8	.01	.00	.01	1.	1.01	12.40	152	.21	.19	.01	350.
1.01	.45	9	.01	.00	.01	1.	1.01	12.45	153	.21	.19	.01	354.
1.01	.50	10	.01	.00	.01	1.	1.01	12.50	154	.21	.20	.01	357.
1.01	.55	11	.01	.00	.01	1.	1.01	12.55	155	.21	.20	.01	360.
1.01	1.00	12	.01	.00	.01	1.	1.01	13.00	156	.21	.20	.01	361.
1.01	1.05	13	.01	.00	.01	1.	1.01	13.05	157	.25	.24	.01	367.
1.01	1.10	14	.01	.00	.01	1.	1.01	13.10	158	.25	.24	.01	384.
1.01	1.15	15	.01	.00	.01	1.	1.01	13.15	159	.25	.24	.01	404.
1.01	1.20	16	.01	.00	.01	1.	1.01	13.20	160	.25	.24	.01	420.
1.01	1.25	17	.01	.00	.01	1.	1.01	13.25	161	.25	.24	.01	429.
1.01	1.30	18	.01	.00	.01	1.	1.01	13.30	162	.25	.24	.01	435.
1.01	1.35	19	.01	.00	.01	1.	1.01	13.35	163	.25	.24	.01	439.
1.01	1.40	20	.01	.00	.01	1.	1.01	13.40	164	.25	.24	.01	441.
1.01	1.45	21	.01	.00	.01	1.	1.01	13.45	165	.25	.24	.01	443.
1.01	1.50	22	.01	.00	.01	1.	1.01	13.50	166	.25	.24	.01	445.
1.01	1.55	23	.01	.00	.01	1.	1.01	13.55	167	.25	.24	.01	446.
1.01	2.00	24	.01	.00	.01	1.	1.01	14.00	168	.25	.24	.01	447.
1.01	2.05	25	.01	.00	.01	1.	1.01	14.05	169	.31	.30	.01	455.
1.01	2.10	26	.01	.00	.01	1.	1.01	14.10	170	.31	.30	.01	479.
1.01	2.15	27	.01	.00	.01	1.	1.01	14.15	171	.31	.30	.01	508.
1.01	2.20	28	.01	.00	.01	1.	1.01	14.20	172	.31	.30	.01	532.
1.01	2.25	29	.01	.00	.01	1.	1.01	14.25	173	.31	.30	.01	546.
1.01	2.30	30	.01	.00	.01	1.	1.01	14.30	174	.31	.30	.01	554.
1.01	2.35	31	.01	.00	.01	1.	1.01	14.35	175	.31	.30	.01	559.
1.01	2.40	32	.01	.00	.01	1.	1.01	14.40	176	.31	.31	.01	562.
1.01	2.45	33	.01	.00	.01	1.	1.01	14.45	177	.31	.31	.01	564.
1.01	2.50	34	.01	.00	.01	1.	1.01	14.50	178	.31	.31	.01	566.
1.01	2.55	35	.01	.00	.01	1.	1.01	14.55	179	.31	.31	.01	567.
1.01	3.00	36	.01	.00	.01	1.	1.01	15.00	180	.31	.31	.01	567.
1.01	3.05	37	.01	.00	.01	1.	1.01	15.05	181	.19	.19	.00	554.
1.01	3.10	38	.01	.00	.01	1.	1.01	15.10	182	.38	.37	.01	530.
1.01	3.15	39	.01	.00	.01	1.	1.01	15.15	183	.38	.37	.01	545.
1.01	3.20	40	.01	.00	.01	1.	1.01	15.20	184	.57	.56	.01	611.
1.01	3.25	41	.01	.00	.01	1.	1.01	15.25	185	.67	.65	.01	740.
1.01	3.30	42	.01	.00	.01	1.	1.01	15.30	186	1.62	1.59	.02	1001.
1.01	3.35	43	.01	.00	.01	2.	1.01	15.35	187	2.67	2.63	.03	1615.
1.01	3.40	44	.01	.00	.01	2.	1.01	15.40	188	1.05	1.04	.01	2362.
1.01	3.45	45	.01	.00	.01	2.	1.01	15.45	189	.67	.66	.01	2605.
1.01	3.50	46	.01	.00	.01	2.	1.01	15.50	190	.57	.57	.01	2310.
1.01	3.55	47	.01	.00	.01	3.	1.01	15.55	191	.38	.38	.00	1813.
1.01	4.00	48	.01	.00	.01	3.	1.01	16.00	192	.38	.38	.00	1413.
1.01	4.05	49	.01	.00	.01	3.	1.01	16.05	193	.29	.29	.00	1116.
1.01	4.10	50	.01	.00	.01	3.	1.01	16.10	194	.29	.29	.00	699.
1.01	4.15	51	.01	.00	.01	4.	1.01	16.15	195	.29	.29	.00	754.
1.01	4.20	52	.01	.00	.01	4.	1.01	16.20	196	.29	.29	.00	661.
1.01	4.25	53	.01	.00	.01	4.	1.01	16.25	197	.29	.29	.00	608.
1.01	4.30	54	.01	.00	.01	4.	1.01	16.30	198	.29	.29	.00	579.
1.01	4.35	55	.01	.00	.01	5.	1.01	16.35	199	.29	.29	.00	561.
1.01	4.40	56	.01	.00	.01	5.	1.01	16.40	200	.29	.29	.00	549.
1.01	4.45	57	.01	.00	.01	5.	1.01	16.45	201	.29	.29	.00	543.
1.01	4.50	58	.01	.00	.01	5.	1.01	16.50	202	.29	.29	.00	541.
1.01	4.55	59	.01	.00	.01	5.	1.01	16.55	203	.29	.29	.00	540.
1.01	5.00	60	.01	.00	.01	6.	1.01	17.00	204	.29	.29	.00	539.

TABLE A-1
Sheet 3 of 5

1.01	5.05	61	.01	.00	.01	6.	1.01	17.05	205	.23	.23	.00	532.
1.01	5.10	62	.01	.00	.01	6.	1.01	17.10	206	.23	.23	.00	508.
1.01	5.15	63	.01	.00	.01	6.	1.01	17.15	207	.23	.23	.00	478.
1.01	5.20	64	.01	.00	.01	6.	1.01	17.20	208	.23	.23	.00	454.
1.01	5.25	65	.01	.00	.01	6.	1.01	17.25	209	.23	.23	.00	441.
1.01	5.30	66	.01	.00	.01	7.	1.01	17.30	210	.23	.23	.00	434.
1.01	5.35	67	.01	.00	.01	7.	1.01	17.35	211	.23	.23	.00	429.
1.01	5.40	68	.01	.00	.01	7.	1.01	17.40	212	.23	.23	.00	427.
1.01	5.45	69	.01	.00	.01	7.	1.01	17.45	213	.23	.23	.00	426.
1.01	5.50	70	.01	.00	.01	7.	1.01	17.50	214	.23	.23	.00	425.
1.01	5.55	71	.01	.00	.01	8.	1.01	17.55	215	.23	.23	.00	424.
1.01	5.60	72	.01	.00	.01	8.	1.01	18.00	216	.23	.23	.00	424.
1.01	6.05	73	.07	.02	.04	10.	1.01	18.05	217	.02	.02	.00	400.
1.01	6.10	74	.07	.02	.04	17.	1.01	18.10	218	.02	.02	.00	320.
1.01	6.15	75	.07	.03	.04	27.	1.01	18.15	219	.02	.02	.00	253.
1.01	6.20	76	.07	.03	.04	35.	1.01	18.20	220	.02	.02	.00	237.
1.01	6.25	77	.07	.03	.04	41.	1.01	18.25	221	.02	.02	.00	221.
1.01	6.30	78	.07	.03	.04	46.	1.01	18.30	222	.02	.02	.00	206.
1.01	6.35	79	.07	.03	.03	50.	1.01	18.35	223	.02	.02	.00	192.
1.01	6.40	80	.07	.03	.03	53.	1.01	18.40	224	.02	.02	.00	179.
1.01	6.45	81	.07	.03	.03	56.	1.01	18.45	225	.02	.02	.00	167.
1.01	6.50	82	.07	.04	.03	59.	1.01	18.50	226	.02	.02	.00	156.
1.01	6.55	83	.07	.04	.03	61.	1.01	18.55	227	.02	.02	.00	146.
1.01	7.00	84	.07	.04	.03	63.	1.01	19.00	228	.02	.02	.00	136.
1.01	7.05	85	.07	.04	.03	65.	1.01	19.05	229	.02	.02	.00	127.
1.01	7.10	86	.07	.04	.03	67.	1.01	19.10	230	.02	.02	.00	118.
1.01	7.15	87	.07	.04	.02	69.	1.01	19.15	231	.02	.02	.00	110.
1.01	7.20	88	.07	.04	.02	71.	1.01	19.20	232	.02	.02	.00	96.
1.01	7.25	89	.07	.04	.02	73.	1.01	19.25	233	.02	.02	.00	90.
1.01	7.30	90	.07	.04	.02	74.	1.01	19.30	234	.02	.02	.00	84.
1.01	7.35	91	.07	.04	.02	76.	1.01	19.35	235	.02	.02	.00	78.
1.01	7.40	92	.07	.04	.02	77.	1.01	19.40	236	.02	.02	.00	73.
1.01	7.45	93	.07	.04	.02	79.	1.01	19.45	237	.02	.02	.00	68.
1.01	7.50	94	.07	.04	.02	80.	1.01	19.50	238	.02	.02	.00	63.
1.01	7.55	95	.07	.05	.02	81.	1.01	19.55	239	.02	.02	.00	59.
1.01	8.00	96	.07	.05	.02	83.	1.01	20.00	240	.02	.02	.00	55.
1.01	8.05	97	.07	.05	.02	84.	1.01	20.05	241	.02	.02	.00	51.
1.01	8.10	98	.07	.05	.02	85.	1.01	20.10	242	.02	.02	.00	48.
1.01	8.15	99	.07	.05	.02	86.	1.01	20.15	243	.02	.02	.00	45.
1.01	8.20	100	.07	.05	.02	87.	1.01	20.20	244	.02	.02	.00	42.
1.01	8.25	101	.07	.05	.02	88.	1.01	20.25	245	.02	.02	.00	39.
1.01	8.30	102	.07	.05	.02	89.	1.01	20.30	246	.02	.02	.00	38.
1.01	8.35	103	.07	.05	.02	90.	1.01	20.35	247	.02	.02	.00	38.
1.01	8.40	104	.07	.05	.02	90.	1.01	20.40	248	.02	.02	.00	38.
1.01	8.45	105	.07	.05	.02	91.	1.01	20.45	249	.02	.02	.00	38.
1.01	8.50	106	.07	.05	.01	92.	1.01	20.50	250	.02	.02	.00	38.
1.01	8.55	107	.07	.05	.01	93.	1.01	20.55	251	.02	.02	.00	38.
1.01	9.00	108	.07	.05	.01	94.	1.01	21.00	252	.02	.02	.00	38.
1.01	9.05	109	.07	.05	.01	94.	1.01	21.05	253	.02	.02	.00	38.
1.01	9.10	110	.07	.05	.01	95.	1.01	21.10	254	.02	.02	.00	38.
1.01	9.15	111	.07	.05	.01	96.	1.01	21.15	255	.02	.02	.00	38.
1.01	9.20	112	.07	.05	.01	96.	1.01	21.20	256	.02	.02	.00	38.
1.01	9.25	113	.07	.05	.01	97.	1.01	21.25	257	.02	.02	.00	38.
1.01	9.30	114	.07	.05	.01	97.	1.01	21.30	258	.02	.02	.00	38.
1.01	9.35	115	.07	.05	.01	98.	1.01	21.35	259	.02	.02	.00	38.
1.01	9.40	116	.07	.05	.01	99.	1.01	21.40	260	.02	.02	.00	38.
1.01	9.45	117	.07	.05	.01	99.	1.01	21.45	261	.02	.02	.00	38.
1.01	9.50	118	.07	.05	.01	100.	1.01	21.50	262	.02	.02	.00	38.
1.01	9.55	119	.07	.05	.01	100.	1.01	21.55	263	.02	.02	.00	38.
1.01	10.00	120	.07	.05	.01	101.	1.01	22.00	264	.02	.02	.00	38.

TABLE A-1
Sheet 4 of 5






PHOTO INDEX I
FOR
DAM

PAUL GOESSLING
ST. LOUIS COUNTY, MO.
OCTOBER 1978

PREPARED BY
REITZ & JENS, INC.





DAIM

D6



D8



D10



D12




D9



D11



DAM



0 100 200 400
FEET

PHOTO INDEX 2
FOR
PANORAMA

PAUL GOESSLING
ST. LOUIS COUNTY, MO.
OCTOBER 1978

PREPARED BY
REITZ & JENS, INC.

P2




P4



P3





PANORAMA



P5





PREPARED BY
REITZ & JENS, INC.

PHOTO INDEX 3
FOR
SPILLWAY

PAUL GOESSLING
ST. LOUIS COUNTY, MO.
OCTOBER 1978



S4



S1




S3



SPILLWAYS


S6



S8



S5



S7







PHOTO INDEX 4
FOR
VALLEY BELOW DAM

PAUL GOESSLING
ST. LOUIS COUNTY, MO.

OCTOBER 1978

PREPARED BY
REITZ & JENS, INC.




V3




VALLEY BELOW DAM

FINAL SURVEY	SURVEYED	BY	LATH
	PIOTTED		
NOTE BOOK	TEMPLATE		
NO	AREAS		
	CHECKED		



PLAN OF DAM AND SPILLWAY







PLAN

0 100








OUTFLOW CHANNEL

4000 6000 FT.

ORIGINAL SURVEY	DATE	
	BY	DATE
DATE BOOK	SURVEYED PLOTTER	
NO.	TEMPLATE	
	AREAS	
	ALIGNED	



.120

.100

.80

0

20

40

60

120

WATER
LEVEL
11 AUG 1978

100

80

0

20

40

FEET PER SECOND

800


1000

1200


1400

1600

Y CAPACITIES





SECTION OF DAM
AT STA. 1+00



SECTION OF DAM
AT STA. 3+50

18





110

**END
DATE
ILME**